

LANAB21377

Installation Instructions

Railing for JD F4365 & 800R Nutrient Applicators

LANKOTA[®]


270 West Park Avenue

Huron, SD 57350

866-526-5682

Parts List

Part Numbers	Description	Qty
LANAKK20834	Railing Weldment	1
LANAKK20835	F4365 Bolt-on End	1
LANAKK20836	800R Bolt-on End	1
REDB308	3/8" x 2" Hex Bolt	2
LANFWS53	3/8" SAE Washer	2
LANFNW7G	3/8" Flange Nyloc Nut	2



Kit Installation

Refer to Figures

1. Remove the factory railing from the machine. Keep the hardware for reinstallation.
2. Attach the appropriate end to the center leg with the 3/8" hardware provided, but leave loose.
 - For F4365 applicators: use LANAKK20835
 - For 800R applicators: use LANAKK20836
3. Set the railing into the outer mount slots and use the original hardware to fasten in place.
4. Tighten the original hardware and then the 3/8" bolts.



Figure 2

Figure 1

For further technical assistance,

Call Lankota Inc. at:

1-866-526-5682