

# **LANMBJD104**

## **Installation Instructions**

**Monitor Bracket Riser Mount for 2020+ JD tractor & Sprayer Cabs**

# **LANKOTA<sup>®</sup>**

**270 West Park Avenue  
Huron, SD 57350  
866-526-5682**


# Parts List

Part Numbers	Description	Qty
LANMBJD104W	Riser Mount	1
LAN19M7784	M10 x 20mm Flange Bolt	2
LANMBJD041	Offset Plate, Corner Cubby	2
LAN18A	3/8" x 1" Carriage Bolt	2
LAN3718	3/8" Serrated Flange Nut	2



# Kit Installation

- 1) Remove the factory cap/plugs from the bottom, corner thread-points.
- 2) Install an M10 bolt on the lower orifice.
- 3) Slide the LANMBJD104W slot over the bolt and fasten with another in the upper hole. Tighten these bolts.
- 4) Install an M10 bolt on the lower threaded hole of the riser.
- 5) Set the corner cubby over the bolt and fasten with another in the upper hole. Tighten all the bolts.



## Kit Installation (Optional)

In some tractors, with some monitors, it may be necessary to extend a mount or corner cubby a little. To do so, this kits includes two off set plates (LANMBJF041).

Use the provided 3/8" hardware to mount them wherever they may be needed.



**For further technical assistance,**

**Call Lankota Inc. at:**

**1-866-526-5682**