

# LANPSP100K

## Installation Instructions

John Deere 90 Series Poly Corn Head Snout Protectors

**Fits 90 Series Corn Heads up to Serial Number 695300**  
**(use LANPSP200K for corn heads above Serial Number 695300)**

# LANKOTA<sup>®</sup>

**270 West Park Avenue**

**Huron, SD 57350**

**866-526-5682**

# Numerical Parts List

Part Numbers	Description	Qty
LANPSP101L	Poly Snout Protector – Left Side	1
LANPSP101R	Poly Snout Protector – Right Side	1
<b>LANPSPBH</b>	<b>Bag of Hardware</b>	<b>1</b>
LAN030114048	3/4" Phillips Pan Head Screw	24
LAN001AB18A32	3/8" x 1.50" Pan Head Bolt	2
LAN3718	3/8" Serrated Flange Nut	2

# Pictorial Parts List



# Preparation

Completely remove corn hood and snout assembly from head and tip on one side.

# Installation

## Refer to Figure 1

1. Remove bolt that hinges on corn snout and hood assembly; see large golden arrow.
2. Fit Stainless Steel Plate (LANPSP101L or LANPSP101R) into position as shown in Figure 1.
3. Reinstall hinge bolt, but do not tighten.
4. Clamp wear plate into position and assure proper fit.
5. Once desired fit is found, attach wear plate on bottom side of snout first using screws (LAN030114048); see small yellow arrows.
6. Install screws from back to front and finish attaching wear strip on top side of snout, see red arrows.
7. Tighten hinge bolt and repeat on other side.

Figure 1

For further technical information,  
contact Lankota Inc. at:  
**1-866-526-5682**

